

## ABNORMAL TEST RESULT

OF MODEL FSB-10, 20, 30

1. Did Cheese Cloth or Paper Glow?

No.

2. Did Ground Fuse Open?

No.

3. Dielectric breakdown?

No.

4. Other Results?

See the following pages .

( FMEA : 2/ 4 ~ 4/ 4)

( Abnormal Test Result: - )

There was no emission of flame, molten metal, ignition of cheesecloth, dielectric breakdown, opening of the ground fuse, other indication of a shock or fire hazard.



F M E A

Component	Mode		Comment	Output Voltage (V)
C11	Open		Normal operation.	
	Short		Normal operation.	
C13	Open		Normal operation.	
	Short		Normal operation.	
C15	Open		Normal operation.	
	Short		Normal operation.	
C21	Open		Normal operation.	
	Short		Normal operation.	
C25	Open		Normal operation.	
	Short		Normal operation.	
C29	Open		Normal operation.	
	Short		Normal operation.	
C41	Open		Normal operation.	
	Short		Normal operation.	
C43	Open		Normal operation.	
	Short		Normal operation.	
C45	Open		Normal operation.	
	Short		Normal operation.	
L11	Open	1or4	No hazard.	AVR1:0
		2or5	No hazard.	AVR1:0
		3or6	No hazard.	AVR1:0
	Short	1-2, 4-5	Circuit breaker operate. No hazard.	AVR1:0
		2-3, 5-6	Circuit breaker operate. No hazard.	AVR1:0
		1-3, 4-6	Circuit breaker operate. No hazard.	AVR1:0



F M E A

Component	Mode		Comment	Output Voltage (V)
L12	Open	1or4	No hazard.	AVR1:0
		2or5	No hazard.	AVR1:0
		3or6	No hazard.	AVR1:0
	Short	1-2, 4-5	Circuit breaker operate. No hazard.	AVR1:0
		2-3, 5-6	Circuit breaker operate. No hazard.	AVR1:0
		1-3, 4-6	Circuit breaker operate. No hazard.	AVR1:0
R11	Open		Normal operation.	
R12	Open		Normal operation.	
R13	Open		Normal operation.	
R21	Open		Normal operation.	
R23	Open		Normal operation.	
R25	Open		Normal operation.	
R41 (Only -335, -355)	Open		Normal operation.	
R42 (Only -335, -355)	Open		Normal operation.	
R43 (Only -335, -355)	Open		Normal operation.	
R44 (Only -335, -355)	Open		Normal operation.	
R45 (Only -335, -355)	Open		Normal operation.	
Harness11	Open		Normal operation.	
Harness12	Open		Normal operation.	
Harness13	Open		Normal operation.	
Harness21	Open		Normal operation.	
Harness22	Open		Normal operation.	
Harness23	Open		Normal operation.	
Harness41	Open		Normal operation.	



F M E A

Component	Mode	Comment	Output Voltage (V)
Harness42	Open	Normal operation.	
Harness43	Open	Normal operation.	